

Oil Field Environmental Incident Summary

Incident: 20141117181520 **Date/Time of Notice:** 11/17/2014 18:15

Responsible Party: Triangle USA Petroleum Corp

Well Operator: TRIANGLE USA PETROLEUM CORPORATION

Well Name: Fritz 150-101-32-29-1H

Field Name: PRONGHORN

Well File #: 21421

Date Incident: 11/17/2014 **Time Incident:** 07:50

Facility ID Number:

County: MCKENZIE

Twp: 150

Rng: 101

Sec: 32

Qtr: SW SE

Location Description: The majority of the flare mist remained on the well location however some of it misted off location onto the road and surrounding vegetation.

Submitted By: Brittany Vannoy

Received By:

Contact Person: Brittany Vannoy
1200 17th Street Suite 2600
Denver, CO 80202

General Land Use: Pasture

Affected Medium: Topsoil

Distance Nearest Occupied Building:

Distance Nearest Water Well:

Type of Incident: Other

Release Contained in Dike: No

Reported to NRC: No

	Spilled	Units	Recovered	Units	Followup	Units
Oil	5	Gallons			0	barrels

Brine

Other

Description of Other Released Contaminant:

Inspected:

Written Report Received: 3/4/2016

Clean Up Concluded: 11/17/2014

Risk Evaluation:

None

Areal Extent:

Potential Environmental Impacts:

Most of the mist was contained to the flare berm, what did leave location was sprayed onto snow. Minimal environmental impact.

Action Taken or Planned:

All of the contaminated snow will be gathered and kept in a containment area until it can be melted and sent to a disposal well.

Wastes Disposal Location:**Agencies Involved:****Updates**

Date: 11/18/2014 **Status:** Inspection**Author:** Stockdill, Scott**Updated Oil Volume:****Updated Salt Water Volume:****Updated Other Volume:****Updated Other Contaminant****Notes:**

Arrived on location 11/18/2014.

Impacted areas on the lease site have been cleaned up; however, there is still a visible sprayed area on the hillside in the farmer's field. Contact was made with the company to clarify what was going to be done with the impact to the field.

More followup is necessary.

Date: 11/18/2014 **Status:** Reviewed - Follow-up Required**Author:** Espe, Brady**Updated Oil Volume:****Updated Salt Water Volume:****Updated Other Volume:****Updated Other Contaminant****Notes:**

Release from the flare sprayed off location. Followup is necessary.

Date: 11/26/2014 **Status:** Inspection

Author: Espe, Brady

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

I arrived at 2:06 p.m. to the site. The weather was 30°F and cloudy, with the wind from the northwest at 10 mph. There were a couple of inches of snow on the ground. The road going into the site sits higher than the pad. The mist went southwest, hitting the sidewall of the road and into a stubble field just south of well. The area on the road has been cleaned up. The impacted soil and snow have been placed on a tarp on the pad; this will be hauled out. Ran into company rep. He was working on contacting the owner of the field to the south; he thought it was the same landowner. He will send information when the landowner has been contacted. Further followup needed. 47 45.692; -103 38.355

Date: 4/1/2015 **Status:** Inspection

Author: Espe, Brady

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

I arrived at the site at 12:38 p.m. The weather is clear, 52°F, with the wind from the west at 30 mph. The area south of pad looks cleaned up. There is an area in the field that is discolored, and the edge of the field is worked up. More followup required.

Date: 4/8/2015 **Status:** Inspection

Author: Espe, Brady

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

I arrived at the site at 16:05 p.m. The weather was cloudy and 46°F, with the wind from the southeast at 10-20 mph. The area of the field sprayed has been worked up. No further followup needed.

Date: 4/16/2015 **Status:** Correspondence

Author: Espe, Brady

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Requested information on the cleanup.

Date: 11/5/2015 **Status:** Correspondence

Author: Espe, Brady

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Requested any documentation the company has about the site.

Date: 11/10/2015 **Status:** Correspondence

Author: Espe, Brady

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

I also talked to the main environmental contact on getting any documentation about the site.

Date: 11/10/2015 **Status:** Inspection

Author: Espe, Brady

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

I arrived at the site at 2:00 p.m. The weather was cloudy, 34°F, with wind from the northwest 10-15 mph. The vegetation in ditches looked good. The field to the south had been cropped this summer and looked good. No further followup is needed at this time.

Date: 2/23/2016 **Status:** Correspondence

Author: Espe, Brady

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Requested documentation about the site.

Date: 3/3/2016 **Status:** Correspondence

Author: Espe, Brady

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Received follow-up spill report.